




No.	ΠΕΡΙΓΡΑΦΗ	ΠΟΣ.
1	Cross recessed pan head tapping screws ST3×9	2
2	Rear cover	1
3	Motor	1
4	Motor holder	1
5	Cross recessed pan head screws M3×6	2
6	Motor pinoin	1
7	Gear housing washer 37.6×16.8×0.5	1
8	Top stair inner gear sleeve	1
9	Top stair planet gear	3
10	Lower stair center gear	1
11	Lower stair inner gear sleeve	1
12	Level Ball	1
13	Cross recessed pan head tapping screws ST2.5×5	2
14	Steel Wire	1
15	Button for high or low speed	1
16	Cross recessed pan head tapping screws ST3×14	4
17	Plastic back housing	1
18	Lower stair planet gear	3
19	The third layer center gear	1
20	Washer	1
21	The third layer inner gear sleeve	1
22	The third layer planet gear	3
23	Spindle	1
24	Spindle washer 20.5×12.5×1.0	1
25	Plastic front housing	1
26	Steel ball 5	12
27	Bear sleeve	1
28	Spindle washer 17.8×12.2×0.5	2

No.	ΠΕΡΙΓΡΑΦΗ	ΠΟΣ.
29	Steel ball 3	15
30	Bearing spring circlip 12	1
31	Torque setting ring washer 40×30.5×0.8mm	1
32	Chuck screw/left twist	1
33	Chuck 10mm	1
34	Torque outter metal sleeve	1
35	Cross recessed pan head tapping screws ST3×20	4
36	Torque clamp plate	1
37	Torque spring plate	2
38	Torque spring plate holder	1
39	Torque	1
40	Bush	1
41	Torque control spring	1
42	Cross recessed pan head tapping screws ST3×14	5
43	Front cover	1
44	Cross recessed pan head tapping screws ST3×14	5
45	Cross recessed pan head tapping screws ST2.2×10	2
46	Right housing	1
47	LED SETS	1
48	F/R shift switch	1
49	Speed variable switch	1
50	12V Li-ion battery	1
51	Power generate lug holder	1
52	Spring washer 3	2
53	Left housing	1
54	12V fast charger	1