



| | |
|----------------------|--------------------------|
| 1 Impact button | 21 Carbom brush |
| 2 Impact piece | 22 Brush nut |
| 3 Screw | 23 Seal ring |
| 4 Label | 24 Bearing bracket |
| 5 Housing(A) | 25 Bearing |
| 6 Chuck Screw | 26 Arnature |
| 7 Spring washer | 27 Stator |
| 8 Chuck | 28 Bearing |
| 9 Big retaining ring | 29 Switch |
| 10 Head crust | 30 Screw |
| 11 Out Alex | 31 Wite holding board |
| 12 Iron shot | 32 Supply Cord |
| 13 Spring | 33 Plug |
| 14 Bearing | 34 Capacitor Capacitance |
| 15 Circlip for shaft | 35 Inductance |
| 16 Circlip for hole | 36 Housing(B) |
| 17 Gear | 37 Button |
| 18 Cirdip for shaft | 38 Staff |
| 19 Iron shot | 39 Side Handle |
| 20 brush cup | |