



No.	ΠΕΡΙΓΡΑΦΗ	ΠΟΣ.
1	Tapping screw	9
2	Housing	1
3	Cord clamp	1
4	Tapping screw	2
5	Cord guard	1
6	Cord	1
7	Tapping screw	2
8	Variable speed PCB	1
9	Stator	1
10	Bearing 6072Z	1
11	Brush holder	2
12	Carbon brush	2
13	Brush holder support	2
14	Rotor	1
15	Bearing 6072Z	1
16	Small bevel gear	1
17	Bearing 6962Z	1
18	Big bevel gear	1
19	Shaft	1
20	Bearing 6272Z	1
21	Counterbalance	1
22	Bearing 6001-2RS	1
23	Small support bar	1
24	Big support bar	1
25	Rubber tube	1
26	Delta ring	1
27	Tapping screw	4
28	Sole plate	1
29	Tapping screw	3
30	Switch slide	1
31	Housing	1
32	Vacuum adaptor	1
33	Inner sleeve of vacuum adaptor	1