



No.	ΠΕΡΙΓΡΑΦΗ	ΠΟΣ.
1	Self-tapping screw ST4×30 (slotted)	4
2	Gearbox WD301	1
3	O-rings Ø3 x Ø18 (inner hole)	1
4	Steel bushing Ø18×Ø24×15.5	1
5	Flat washer Ø30×Ø18.6×0.5	1
6	output shaft WD301	1
7	Steel ball 5.5	2
8	Impact block	1
9	Steel ball 4.5	20
10	Flat washer Ø34.4×Ø26.6×1	2
11	Spring Ø35×36	1
12	Inner shaft WD301	1
13	Planetary gear 21	3
14	Cylindrical pin Ø6×16	3
15	Flat washer 16	1
16	Bearing 6002	1
17	Gear ring 50	1
18	Support frame WD301	1
19	Bearing 6000	1
20	Rotor WD301	1
21	Bearing 607	1
22	Stator WD301	1
23	Right Housing WD301	1
24	Screw ST4×16	10
25	Brush holder cap	2
26	Carbon brushes 6×9×14	2
27	Brush holder 6×9	2
28	Tension spring	2
29	Brush holder support	1
30	Round inductance	2
31	Left housing WD301	1
32	Power indicator	1
33	Indicator lamp shade-Transparent	1
34	Reverse push button 3181	1
35	Switch WD301	1
36	Capacitance 0.47µF(3-pins)	1
37	Torsion spring - capacitance	1
38	Cable clamp 15.5	1
39	Cable protect cover (13 punching)	1
40	Rubber cable 2×1.0mm2	1