




**ΥΠΟΒΡΥΧΙΑ ΑΝΤΛΙΑ ΠΛΑΣΤΙΚΗ
ΟΜΒΡΙΩΝ ΥΔΑΤΩΝ 400W**



No	Spare Parts list
1	power cable&plug
2	Float switch
3	screws
4	washer
5	rear punp casting
6	cable jacket
7	cable compaction buckle
8	capacity
9	cable compaction board
10	screws
11	rear cover
12	corrugated gasket
13	bearing

No	Spare Parts list
14	rotor
15	stator
16	front cover
17	oil seal
18	skeleton seal
19	impeller
20	main pump housing
21	steel ball
22	washer
23	screws
24	oil seal
25	base
26	screws