



No.	ΠΕΡΙΓΡΑΦΗ	ΠΟΣ.
1	Anterior shell	1
2	Long handle	1
3	Switch knob	1
4	Upper cover of switch box	1
5	Rotary switch	1
6	O2 Motor hood	1
7A	Motor pump	1
7B	Motor	1
8	Posterior shell	1
9	Base	1
10	Cross pan head self tapping screw	13
11	Wire clamp	1
12	Wheels	2
13	Cross pan head self tapping screw	13
14	Power cord	1
15	Inner filter	1
16	Inner hose	1
17	Inner quick connector	1
18	Steel needle	1
201	Foam bottle	1
202	High press. gun mounting base	1
203	Power cord mounting base	1
204	Bypass switch	1
205	Valve	1