



1 Impact button	21 Carbom brush
2 Impact piece	22 Brush nut
3 Screw	23 Seal ring
4 Label	24 Bearing bracket
5 Housing(A)	25 Bearing
6 Chuck Screw	26 Arnature
7 Spring washer	27 Stator
8 Chuck	28 Bearing
9 Big retaining ring	29 Switch
10 Head crust	30 Screw
11 Out Alex	31 Wite holding board
12 Iron shot	32 Supply Cord
13 Spring	33 Plug
14 Bearing	34 Capacitor Capacitance
15 Circlip for shaft	35 Inductance
16 Circlip for hole	36 Housing(B)
17 Gear	37 Button
18 Cirdip for shaft	38 Staff
19 Iron shot	39 Side Handle
20 brush cup	